Drawing Name

Part Number

Material

Due Date

Drawing Number

Project Number

Drawing Revision

Qty:

10 Um:

Each

: STEP WELDMENT

: D2563

: N/A

: NIA

: 2/9/2007

· D2563 REV C

Previous Run Written By Checked & Approved By Job Number: Seq. #:

Monday, 1/22/2007 7:45:36 AM

Kim Johnston

Process Sheet

: CU-DAR001 Dart Helicopters Services Customer

Job Number : 30343 **Estimate Number** : 10176

: NIA P.O. Number

: 1/22/2007 This Issue

Prsht Rev. : NC : MA First Issue

Type

: LARGE FAB ASSY

S.O. No. : NA

Comment

: 29537

Re-format Location RF

Additional Product



2.0

Machine Or Operation:

Description: Step Extrusion

1.0 D2244116

Comment: Qty.:

1.0000 Each(s)/Unit Total:

Total:

10.0000 Each(s)

Pick:

Step Extrusion

2.0000 Each(s)/Unit

20.0000 Each(s)

Pick:

Qtv Part No.

Description

D2673-34 2

End Cap

D2561 3.0

Comment: Qty.:

Lug Plate

Comment: Qty.:

2.0000 Each(s)/Unit Total:

20.0000 Each(s)

Pick:

Part No. Qty

D2561

Description Lug Plate

4.0

2 D2564

2.0000 Each(s)/Unit Total:

20.0000 Each(s)

Comment: Qty.: Pick:

2

Qty Part No. D2564

Description

Mounting Angle

Dart Aerospace Ltd

W/O:			WORK ORDER C	HANGES				
DATE	STEP	PRO	OCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			,					
Part No):	PAR #:	Fault Category:	NCR: Yes	No DQ	A :	Date:	

Part No: _	 PAR #:	Fault Category:	NCR: Yes N	o DQA :	Date: _	· · · · · ·
			QA: N/C	Closed:	Date: _	

NCR:		,	WORK ORE	ER NON-CONFORMANCE (NCR)						
		Description of NC		Corrective Action Section E	B	Verification	Approval			
DATE	STEP Description of NC Initial Act	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector				
				•						
							-			
				en e						

NOTE: Date & initial all entries



Monday, 1/22/2007 7:45:36 AM Date: Kim Johnston User: **Process Sheet** Drawing Name: STEP WELDMENT Customer: CU-DAR001 Dart Helicopters Services Job Number: 30343 Part Number: D2563 Job Number: Seq. #: Machine Or Operation: Description: LARGE FABRICATION RESOURCE 1 LARGE FAB 1 5.0 Comment: LARGE FABRICATION RESOURCE 1 1-Cut D2244 to 89.70" at 34° as per Dwg D2563 . St. 07-01.31 2-Deburr ends 3-Weld (1 End CAP, LUG PLATES & MOUNTING ANGLE as per Dwg D2563 using DT 8343 Batch: <u>M/80287</u> M02825 AL ROD 4-Grind WELD INSPECTION 6.0 QC5/9 Comment: WELD INSPECTION 7.0 HAND FINISHING1 HAND FINISHING RESOURCE #1 Comment: HAND FINISHING RESOURCE #1 Chemical Conversion Coat as per QSI 005 4.1 8.0 QC3 AT/CHEMICAL CONVERSION Comment: INSPECT POWDER COAT/CHEMICAL CONVERSION 9.0 LARGE FABRICATION RESOURCE 1 Comment: LARGE FABRICATION RESOURCE 1 1-Inspect for foreign object per QSI 024 2-Weld Remainig End as per Dwg D2563 using DT 8343 Batch: <u>MICD 237</u> AL ROD 3-Grind 10.0 QC9 Comment: VISUAL WELDING INSPECTION

Dart	Aeros	pace	Ltd
-------------	--------------	------	-----

	WORK ORDER CHANGES	WORK ORDER CHANGES						
STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
						,		
	STEP	STEP PROCEDURE CHANGE	STEP PROCEDURE CHANGE By	STEP PROCEDURE CHANGE By Date	STEP PROCEDURE CHANGE By Date Qty	STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr		

Part No:	1/	_ PAR #:	Fault Category:	NCR: Yes Nø	DQA	Date: <u>07/0</u>	94 19
			•	QA: N/C	Closed:	Date:	

NCR:		WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval	Approval			
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector			
				` .							
		Š		•							
		•									
	•				i						

NOTE: Date & initial all entries



Date:	Monday, 1/22/2007 7:45:36 AM				1
User:	Kim Johnston	Process S	heet		
Custo	omer: CU-DAR001 Dart Helicopters	s Services Draw	wing Name: STEP WELD	MENT	
loh Nur	mber: 30343	De	art Number: D2563		
Job Number	<u> </u>		art Number, 52000		
Seq. #:	Machine Or Operation:		Description :		
11.0	QC5	<i>[</i>]	TO CURRENT STEP		10
	omment: INSPECT WORK TO C	JRRENT STEP			
12.0	POWDER COATING	POWDER COATI!	NG		
Co	omment: POWDER COATING			,	
	Touch up Alodine then Powder Coat White Glo	C: 100 ss (Ref: 4.3.5.1) as per QSI 005 4.3	G_{m}	07/02/06	110
13.0	HAND FINISHING1	HAND FINISHING	RESOURCE#1		
Co	omment: HAND FINISHING RES		/	1/2/1	1
14.0	Wing Walk as per Dwg I		103004 ER COAT/CHEMICAL CONV	a.M 07/02/01 TERSION	10)
15.0	omment: INSPECT POWDER CC QC21	AT/CHEMICAL CONVERSION FINAL INSPECTION	DN/W/O RELEASE	1102/k (10)	-
			, ,		
Co	omment: FINAL INSPECTION/W/	O RELEASE		Portoalla	-
Job Completion			L	1 07.0209	
				•	

Dart Aerospace Ltd

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
	,						
Part No	:	PAR #: Fault Category: NO	R: Yes	s No DQ	A:	Date:	

NCR:			WORK ORDER NON-CONFORMANCE (NCR)									
		Description of NC		Corrective Action Section B		Verification	Approval Chief Eng	T .				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C		Approval QC Inspector				
				e rac								
						-						
								-				
ė												
				·								

NOTE: Date & initial all entries

QA: N/C Closed: ____ Date: ___

